

# JAGUAR

## Spares Division

Subject: CONTROL CABLE END FITTING

Model affected: All Mark 2 models.

Section: BUMPING

Bulletin No. R.4

Sheet: 1 of 1

Date: April 1960

Introduced at:

The item shown in the Mark 2 Spare Parts Catalogue under the above Title is incorrect. Will all concerned please make the following alteration on Page 530.

(1) Alter Part No. C.15724 to read C.13824

(2) Alter description "End Fitting" to read "Clip"



### ENDORSE YOUR SPARE PARTS CATALOGUE

Page 530  
Page  
Page

Publication No. J.28.  
Publication No.  
Publication No.

Page  
Page  
Page

Publication No.  
Publication No.  
Publication No. Jaguar Cars Limited 2005

# JAGUAR

## Spares Division

Subject: GOLD AIR CONTROL

Model affected:

- 2.4 Litre Mark 2
- 3.4 Litre Mark 2
- 3.8 Litre Mark 2

Section HEATING

Bulletin No. R.5

Sheet: 1 of 3

Date: June 1960

Introduced at: Chassis number		
R.H. Drive	L.H. Drive	
102348	125529	
151568	175697	
201145	212774	

Commencing at the above Chassis numbers and on all subsequent Mark 2 cars a water valve is introduced in the pipe leading to the heater radiator to cut off the flow of water through the heater radiator when the "COLD" air position is selected. The flap on the heater case is coupled with the water valve to operate simultaneously upon movement of the "Hot/Cold" lever.

The modified items, details of which are shown below, are not interchangeable with those previously fitted.

<u>Part No.</u>	<u>Description</u>	<u>No. off</u>	<u>Remarks</u>
C.16778	CASE ASSEMBLY FOR HEATER	1	
C.16776	Lid for Heater Case	1	
C.16762	FEED PIPE FROM INLET MANIFOLD TO HEATER	1	2.4 LITRE CARS ONLY
C.16763	FEED PIPE FROM INLET MANIFOLD	1	3.4 AND 3.8 LITRE CARS ONLY
C.8145	ELBOW HOSE CONNECTING FEED PIPE TO WATER RADIATOR AND REAR RETURN PIPE TO HEATER	2	

### ENDORSE YOUR SPARE PARTS CATALOGUE

Page 526  
Page 527  
Page 528

Publication No. J.28  
Publication No. J.28  
Publication No. J.28

Page 529  
Page 530  
Page

Publication No. J.28  
Publication No. J.28  
Publication No.

# JAGUAR Spares Division

SECTION  
HEATING

Bulletin No R.5

(continued)

Date: June 1960

Sheet: 2 of 3

<u>Part No.</u>	<u>Description</u>	<u>No. off</u>	<u>Remarks</u>
C.16789	LEVER ASSEMBLY "HOT" AND "COLD" CONTROL	1	
C.15597	Lever only	1	
C.16685	Bracket Assembly for Lever	1	
UFB.125/7H	Bolt pivoting Control Lever	1	
C.8737/1	Nut, Self Locking, on Bolt	1	
FW.104/T	Washer, Plain, under Nut	1	
C.15712	Spacer on Bolt	1	
BD.11721	Inner Attachment Pin	1	
UCS.113/2H	Screw, Set, securing Attachment Pin to Lever	1	
C.8667/20	Nut on Setscrew	1	
OW.104/T	Washer, Plain, under Nut	1	
C.11943	Outer Clamp	1	
UFS.119/2H	Screw, Set, securing Outer Clamp to Bracket	1	
C.8667/17	Nut on Setscrew	1	
AW.102/T	Washer, Plain, under Nut	1	
C.16793	OUTER CABLE FOR "HOT/COLD" CONTROL	1	
C.16794	INNER CABLE FOR "HOT/COLD" CONTROL	1	
BD.11455	PLATE INSCRIBED "HOT/COLD" BEHIND L H ESCUTCHEON	1	
C.16559	WATER VALVE ASSEMBLY (FW.1901/2)	1	
C.9928	Sealing Ring for Water Valve (CHS.4653)	1	
C.9931	Screw securing Water Valve to Heater Case	2	
C.9932	Spring, Washer, on Screw	2	
C.10351	Trunnion for Joint of Inner Cable to Valve (CHS.4097)	1	
C.10352	Screw, securing Inner Cable in Trunnion	1	

Jaguar Cars Limited 2005

ENDORSE YOUR SPARE PARTS CATALOGUE (See Sheet 1 of this Bulletin)

# JAGUAR Spares Division

SECTION  
HEATING

Bulletin No R.5. (continued)

Date: June.1960

Sheet: 3 of 3

<u>Part No.</u>	<u>Description</u>	<u>No.off</u>	<u>Remarks</u>
C.16614	WIRE CABLE, LINKING WATER VALVE TO FLAP ON HEATER CASE	1	
C.17409	Trunnion for Joint of Link Cable to Valve and Flap (CH.36209/05)	2	
C.17443	Screw, securing Link Valve in Trunnions	2	



Jaguar Cars Limited 2005

ENDORSE YOUR SPARE PARTS CATALOGUE (See Sheet 1 of this Bulletin)

# JAGUAR

## Spares Division

Subject: IMPROVED HEATER FLAP OPERATION

Model affected:

2.4 litre Mark 2  
 3.4 litre Mark 2  
 3.8 litre Mark 2

Section: HEATING

Bulletin No: R.9

Sheet: 1 of 1

Date: October, 1963.

Introduced at: Chassis number  
 R.H. Drive L.H. Drive  
 116069 127302  
 164310 179493  
 231563 223123

Mark 2 cars bearing the above and subsequent chassis numbers are fitted with a modified Heater Case and revised Air Flap/Heater Valve Link Cable, which permit improved Flap Operation. The parts introduced by this modification may, if desired, be fitted as replacements for their predecessors, provided that both new items are employed.

<u>Part No.</u>	<u>Description</u>	<u>No. off</u>
C. 21991	HEATER CASE ASSEMBLY	1
C. 21992	WIRE CABLE LINKING WATER VALVE TO FLAP ON HEATER CASE	1

### ENDORSE YOUR SPARE PARTS CATALOGUE

Page 90  
 Page  
 Page

Publication No. J. 28/2  
 Publication No.  
 Publication No.

Page 96  
 Page  
 Page

Publication No. J. 28/2  
 Publication No. Limited 2005  
 Publication No.