

JAGUAR

Spares Division

Subject : **PARCEL TRAYS AND CRASH ROLLS**

Model affected :

4.2 'E' Type 2+2

Section : **BODY**

Bulletin No. : **P.196 (2nd issue)**

Sheet : **1 of 1**

Date : **July, 1968.**

Introduced at : **Chassis number**

R.H.Drive L.H.Drive
1E.50681 1E.77377

This Bulletin supersedes the original issue of Spares Bulletin P.196 dated January, 1968, which should be destroyed.

Commencing at the above chassis numbers, modified Parcel Trays are fitted to 4.2 'E' Type 2+2 models. The Parcel Tray Crash Rolls are also modified and the new parts may, if desired, be fitted, IN SETS, to earlier 2+2 car.

Details are shown in this Bulletin.

<u>Part No.</u>	<u>Description</u>	<u>No. off</u>	<u>Remarks</u>
BD.30254	PARCEL TRAY ASSEMBLY, R.H.	1	R.H. DRIVE CARS ONLY
	Individual items are as for Parcel Tray BD.28543		
BD.30256	PARCEL TRAY ASSEMBLY, L.H.	1	L.H. DRIVE CARS ONLY
BD.30255	PARCEL TRAY ASSEMBLY, R.H.	1	
BD.30257	PARCEL TRAY ASSEMBLY, L.H.	1	
	Individual items are as for Parcel Tray BD.28546		
BD.30263	CRASH ROLL ASSEMBLY ON R.H. PARCEL TRAY	1	
BD.30264	CRASH ROLL ASSEMBLY ON L.H. PARCEL TRAY	1	

ENDORSE YOUR SPARE PARTS CATALOGUE

Page 200

Page

Page

Publication No.

Publication No.

Publication No.

J.38

Page

Page

Page

Publication No.

Publication No.

Publication No.

JAGUAR

Spares Division

Subject : MOTIF BAR AND MOUNTINGS

Model affected :

4.2 'E' Type Open
 4.2 'E' Type Fixed Head Coupe
 4.2 'E' Type 2 + 2

Section : BODY
 Bulletin No. : P. 197.

Sheet : 1 of 1

Date : January, 1968.

Introduced at : Chassis number
 R.H. Drive L.H. Drive
 1E. 1712 1E. 14583
 1E. 21473 1E. 34147
 1E. 50710 1E. 77047

Commencing at the above chassis numbers, a revised Motif Bar, together with modified Rubber Mountings, is fitted to 4.2 'E' Type models. The new parts, which were also fitted to certain individual cars prior to those shown above, are interchangeable, IN CAR SETS, with their predecessors.

Details are shown below:-

<u>Part No.</u>	<u>Description</u>	<u>No. off</u>
BD.17700/1	MOTIF BAR IN AIR INTAKE APERTURE	1
BD.24448/1	Rubber Mounting, between Motif Bar and Bumper Extensions	2

ENDORSE YOUR SPARE PARTS CATALOGUE

Page 159
 Page 210
 Page

Publication No. J. 37
 Publication No. J. 37
 Publication No.

Page 188
 Page
 Page

Publication No. J. 38
 Jaguar Cars Limited 2005
 Publication No.
 Publication No.

JAGUAR

Spares Division

Subject : BONNET AND FINISHING ITEMS

Model affected :

- 4.2 'E' Type Open
- 4.2 'E' Type Fixed Head Coupe
- 4.2 'E' Type 2 + 2

Section : BODY

Bulletin No. : P.198(See also Q.143)

Sheet : 1 of 3

Date : January, 1968.

Introduced at :
 Chassis number
 R.H.Drive L.H.Drive
 1E.1864 1E.15889
 1E.21584 1E.34550
 1E.50975 1E.77645

Commencing at the above chassis numbers, the Bonnet and Front Wings Assembly fitted to 4.2 'E' Type models is modified to provide direct access to the Headlamps.

The parts introduced by this modification are shown in this Bulletin, and Headlamp changes are detailed in Spares Bulletin Q.143.

Distributors and Dealers are urged to note that, with the exception of the cars listed at the end of this Bulletin, the new Bonnet and Front Wings Assembly was introduced ON CARS EXPORTED TO CANADA AND U.S.A. at chassis number 1E.14532(L.H.Drive Open), 1E.34113(L.H.Drive Fixed Head Coupe) and 1E.77010(L.H.Drive 2 + 2).

Part No.	Description	No.off
BD.28379	BONNET AND FRONT WINGS ASSEMBLY	1
BD.30935	Centre Panel Assembly, for Bonnet	1
BD.28380	R.H.Front Wing Assembly	1
BD.28381	L.H.Front Wing Assembly	1
BD.28428	Filler Panel Assembly, mounting R.H.Headlamp	1
BD.28429	Filler Panel Assembly, mounting L.H.Headlamp	1
BD.28460	R.H.Front Diaphragm Assembly	1
BD.28461	L.H.Front Diaphragm Assembly	1
All other items are as for Bonnet and Front Wings Assembly		
	BD.29366	
BD.28539	Drain Tube(P.V.C.) for Headlamp Filler Panels	2
C.5648	Rubber Plug, in Front Diaphragms	2

ENDORSE YOUR SPARE PARTS CATALOGUE

Page 52
 Page 59
 Page 04

Publication No. J.37
 Publication No. J.37
 Publication No. J.37

Page 10
 Page 82
 Page 88

Publication No. J.37
 Jaguar Cars Limited 2005
 Publication No. J.38
 Publication No. J.38

JAGUAR Spares Division

SECTION

Bulletin No.:

(continued)

Date:

P.198(See also Q.143)

January, 1968.

BODY

Sheet:

2 of 3

<u>Part No.</u>	<u>Description</u>	<u>No.off</u>
BD.31130	CHROME FINISHER AT R.H.SIDE OF R.H.HEADLAMP APERTURE	1
BD.31132	CHROME FINISHER AT L.H.SIDE OF R.H.HEADLAMP APERTURE	1
BD.31252	Beading(P.V.C.) under R.H.Chrome Finishers	1
BD.31133	CHROME FINISHER AT R.H.SIDE OF L.H.HEADLAMP APERTURE	1
BD.31131	CHROME FINISHER AT L.H.SIDE OF L.H.HEADLAMP APERTURE	1
BD.31253	Beading(P.V.C.)under L.H.Chrome Finishers	1
BD.31095/2	Retainer and Rivet, fixing Chrome Finishers and securing Filler Panels	18
AW.105/T	Plain Washer, on Rivets	18
BD.31129	JOINT PIECE FOR HEADLAMP APERTURE FINISHERS	2
DA.008/8S	Self-Tapping Screw, securing Joint Pieces	2
BD.28422	CHROME FINISHER ASSEMBLY ABOVE R.H.HEADLAMP	1
BD.28423	CHROME FINISHER ASSEMBLY ABOVE L.H.HEADLAMP	1
DAZ.806/6C	Self-Tapping Screw, securing Chrome Finishers	4
BD.19029/4	CHROME BEADING AT REAR OF HEADLAMP APERTURES	2
BD.19030	Clip(Brass) securing Chrome Beadings	14

JAGUAR Spares Division

SECTION

Bulletin No.:

(continued)
P.198(See also Q.143)

Date:

January, 1968.

BODY

Sheet:

3 of 3

The following cars EXPORTED TO CANADA AND U.S.A. were NOT FITTED with the new items listed in this Bulletin:-

<u>L.H. Drive Open C</u>	<u>L.H. Drive Fixed Head Coupe</u>	<u>L.H. Drive 2 + 2</u>
1E. 14534	1E. 34114 to 1E. 34117	1E. 77019
1E. 14536	1E. 34130	1E. 77026 to 1E. 77029
1E. 14537	1E. 34139	1E. 77048
1E. 14540 to 1E. 14544	1E. 34212	1E. 77059
1E. 14559 to 1E. 14561		
1E. 14590 to 1E. 14592		
1E. 14595		
1E. 14643		
1E. 14655		
1E. 14656		



Jaguar Cars Limited Printed in England

ENDORSE YOUR SPARE PARTS CATALOGUE (See Sheet 1 of this Bulletin)