

PARTS OPERATIONS



# Parts Technical Information

Parts Technical Services  
Facsimile No. (0)1203 404036

**DATE:** December 1994

**P.T.I. :** 178

**FICHE:** RTC 9910 FH  
RTC 9918 FF  
RTC 9922 FC

**MODELS:** XJS Range  
Jaguar Saloon Range  
The New XJ Series

**SUBJECT:** JLM 11649 - Cylinder Head Gasket Set

Gasket Sets bought prior to 12/12/94 may incorrectly contain EBC 3531 - Seal-Valve Stem.

These are not suitable for 7 mm diameter Valve Stems and should be substituted with EBC 3956 (Quantity 24).

VS6043

## Parts Technical Information

Parts Technical Services  
Telephone No. (0) 203 307767  
Facsimile No. (0) 203 305625

**DATE:** November 1991

**P.T.I.:** 147

**MODELS:** XJS Range from (V)179737

**FICHE:** RTC 9910

**GROUP:** Engine

**SUBJECT:** Oil Transmitter

**REASON FOR CHANGE:**

An incorrect Part Number for the Oil Transmitter has been advised in the Fiche.

3 46272 is an incorrect Part Number for this Fiche Application.

3A0 3379 is the correct Part Number.

**N.B.** 3 46272 is fitted to cars prior to (V)179736.

## Parts Technical Information

Parts Technical Services  
Telephone No. (0) 203 402121  
Facsimile No. (0) 203 404036

DATE: May 1993

P.T.I.: 165

MODELS: Saloon Range  
XJS Range

FICHE: RTC 9918  
RTC 9910

SUBJECT: Radio/Cassette Players

### REASON FOR CHANGE:

Please note the following Radio Cassette Players were introduced at the VIN Numbers shown below and are not interchangeable with Radio Cassette fitted to vehicles prior to these VIN Numbers. This is due to speaker incompatibility on the Saloon Range and the incorporation of the telephone mute system on the XJS Range.

### SALOON RANGE

DBC 11303	Weather Band (WB)	{
DBC 11304	Radio Data Service (RDS)-Jaguar	{
DBC 11305	Loud (LD)	{ From (V)667829
DBC 11306	Traffic-Japan only	{
DBC 11307	Radio Data Service (RDS)-Daimler	{

### XJS RANGE

DAC 7613	Radio Data Service (RDS)	From (V)186981
DAC 7614	Weather Band (WB)	From (V)187585
DAC 7615	Traffic-Japan only	From (V)188105
DAC 7616	Loud (LD)	From (V)186981

## Parts Technical Information

Parts Technical Services  
Telephone No. (0) 203 307767  
Facsimile No. (0) 203 305625

**DATE:** January 1993

**P.T.I.:** 161

**MODELS:** XJS range  
XJ6 range

Series III 5.3 Litre

**FICHE:** RTC 9910  
RTC 9893 &  
RTC 9918  
RTC 9898

**SUBJECT:** Steering Racks

**REASON FOR CHANGE:**

Page 1 on P.T.I. No. 160 issue 2 showed an incorrect Part Number **JZS 100019** for the Washer. The correct Part Number is **JZW 100019** and is shown below.

