




Parts Technical Information



Volume: J8
Number: ~~36~~ J2
DATE: November 1989

ITEM: 48

MODELS: XJS

FICHE: RTC9900

GROUP: Bodyshell & Fitting

SUBJECT: Gasket - Bumper Mounting

REASON FOR CHANGE: Parts Technical Information VJ8 No. J4 Item 43 lists the plain washer as BEC 1990. This is incorrect. The correct part number should be BEC 1900.

New Part No.	QTY	Description	Existing Part No
BEC1900	6	Plain Washer	WC108051J

Volume:J8
Number:J6
DATE:November 1989

ITEM: 61

MODELS: XJS 3.6 litre


FICHE: RTC9900

GROUP: Brakes and Brake Controls

SUBJECT: Hydraulic Pipes

REASON FOR CHANGE: Introduction of new hydraulic pipes from pump unit to connectors.

New Part No.	QTY	Description	Existing Part No	Remarks
CBC7717	1	Hyd. Pipe - Connector to Pump	CBC2650	RHD
CBC7716	1	Hyd. Pipe - A/S Unit to Pump	CBC6174	LHD



JAGUAR