




Parts Technical Information



Volume: J8
Number: ~~36~~ J2
DATE: November 1989

ITEM: 48

MODELS: XJS

FICHE: RTC9900

GROUP: Bodyshell & Fitting

SUBJECT: Gasket - Bumper Mounting

REASON FOR CHANGE: Parts Technical Information VJ8 No. J4 Item 43 lists the plain washer as BEC 1990. This is incorrect. The correct part number should be BEC 1900.

New Part No.	QTY	Description	Existing Part No
BEC1900	6	Plain Washer	WC108051J

Volume:J8
Number:J6
DATE:November 1989

ITEM: 55

MODELS: XJS


FICHE: RTC9900

GROUP: Facia, Trim, Seats & Fixings

SUBJECT: Spare Wheel Fixings

REASON FOR CHANGE: Introduction of new fixing method for
the spare wheel.

New Part No.	QTY	Description	Existing Part No	Remarks
CBC5629	1	Hook Bar Assy	CAC5099	
CBC5627	1	Spare Wheel Clamp Nut	-	



JAGUAR